ZONE 5 /// ATION Transactions and Consulting

Exclusively Presents: 2002 Falcon 900EX, SN 103

2002 Falcon 900EX - SN 103

Engine and APU Programs | Two Owners Since New | Professionally Managed and Flown



2002 Falcon 900EX

AIRFRAME

Registration N900HD

Serial Number 103

Total Hours 7664

Total Landings 3266

ENGINES	Left Engine	Center Engine	Right Engine
Model		Garrett TFE731-60-1C	
Serial Number(s)	P112422	P112423	P112424
Total Hours	7317	7580	7580

3238

Enrolled on Engine MSP Gold Program

APU

Model Honeywell GTCP 36-150F

3144

Serial Number P-420
Total Hours 4176

Enrolled on APU MSP Gold Program

Current January 20, 2025

3238

AVIONICS

- Honeywell Primus Elite w/5-Tube EFIS upgrade with Synthetic Vision and Charts
- DU 875 Elite II New version 830 FMS Mark 2 CDU
- FANS 1A compliant with CPDLC and ADS-C
- Flight Dynamics HGS-2860 HUD-Cat IIIA
- Triple Honeywell NZ-2000 FMS, Touchscreens with Software 6.1.1 Upgrade
- Dual Collins VHF-422C Comms
- Dual Collins VIR-432 Navs
- Dual Collins ADF-462
- Dual Collins DME-442
- Dual Collins TDR-94D Mode S Transponder w/ADS-B Out
- Dual Collins HF-9000
- Coltech CSD-714 SELCAL (2 Ch.)
- Honeywell Primus 880 Weather Radar
- Dual Honeywell AA-300 Radio Alts
- Honeywell AP/Auto-throttles
- Dual Honeywell WAAS/GPS (LPV)
- Triple Laseref IV IRS
- Collins TCAS 4000 (7.1)
- MK V EGPWS
- Honeywell SSCVR, Honeywell SSFDR-57 Parameters
- Socata ELT 97-406 (406 MHz) ELT
- SATAFIS

The information contained herein does not constitute an offer, commitment, representation, guarantee or warranty of any kind, and is subject to change without prior notice. This information has been provided in good faith. Verification of specifications is the responsibility of the buyer. Aircraft is subject to prior sale or withdrawed from the parket. Block gradity to Acon Aviation Photography.

2002 Falcon 900EX

INTERIOR

Twelve (12) passenger interior consisting of a forward four (4) place club, mid cabin four (4) place dining group opposite a credenza, and an aft three (3) place divan opposite an executive work station.

Chatham leather seats in Fallow (tan), Pindler & Pindler Muslim divan in Mink (dark brown), tan carpeting, Chestnut Burl Birdseye Maple cabinetry, 24K Satin Gold hardware, Tapis Corporation leather upper sidewalls in Ostrich (light beige), Edelman leather lower sidewalls in Ore (dark brown) & Pollack Secret Garden sidewall & lavatory accents in Serpia.

Forward full service 36" galley has a TIA automatic coffee maker, two (2) TIA high temperature ovens, ice chest, cold storage chest, TIA Wavejet microwave, & storage.

Forward and aft lavatories.

EXTERIOR

Allover white with red and blue stripping.

ransactio

COMMUNICATIONS / ENTERTAINMENT

- Collins SAT-6000 Aero H+ SATCOM
- GoGo WIFI Internet
- Airshow Genesys, multi region DVD, 10 disk CD player, VCR, one 18" and one 15" bulkhead mounted monitor. Three (3) Rosen 5.6" LCD plug-in monitors and stereo speakers.

Additional Notes

- Increased MTOW SE
- CAMP

- High Altitude Landing SB
- Teleflex Recognition Light System

MAINTENANCE

- 12 Month Inspection Due October 25, 2025
- 24 Month / 1600 HR Inspection Due December 10, 2026
- 36 Month / 2400 HR Inspection Due October 25, 2026
- 1B Inspection Due at 9,181.3 Hrs
- 2B Inspection Due at 9,080.3 Hrs
- 3B Inspection Due at 9,080.3 Hrs
- 1C/2C Inspection Due December 10, 2026

For more maintenance information:

Status Report

24 Month Due List

AD/SB Master List

ZONE 5 AVIATION | www.zone5jets.com

The information contained herein does not constitute an offer, commitment, representation, guarantee or warranty of any kind, and is subject to change without prior notice. This information has been provided in good faith. Verification of specifications is the responsibility of the buyer. Aircraft is subject to prior sale or withdrawal from the market. Photo credits to Acon Aviation Photography.















ZONE 5 AVIATION | www.zone5jets.com









ZONE 5 AVIATION

Transactions and Consulting